


TYPICAL PATCH REPAIR

MEMTECH TITAN / R1 / M1 / MEMBRANE

CUT OR DAMAGE TO MEMBRANE



MEMTECH TITAN / TITAN TANK / R1 / M1 /
PATCH TO EXTEND MINIMUM 150mm FROM
DAMAGED AREA IN ALL DIRECTIONS

JOINTS TO BE HEAT WELDED / DOUBLE SEALED
WITH MEMTECH GAS TAPES



**MEMTECH
MEMBRANES**

DRAWING No: DGS-325-1

DRAWING TITLE: MEMTECH - TYPICAL PATCH REPAIR

DELTA HOUSE, MERLIN WAY, NORTH WEALD, EPPING, ESSEX CM16 6HR
TEL: 01992 523523 FAX: 01992 523250

OFFICE USE:

REVISION No:
1

REVISION DATE:
April 2018

Drawn By:
Checked By:
Scale:
System Files: PDF / DWG

DRAWING NOTE:

This drawing is for
illustrative purposes
only. Drawing not to
scale.

PROJECT / COMMENTS:

DRAWING
NOTES:

Memtech Titan provides both a waterproof membrane and Hydrocarbon
and VOC barrier in accordance with BS 8102 (2009) and BS 8485: 2015